


BLAIR HILL WIND FARM

FIGURE 8.5 OVERVIEW

PEATLAND CONDITION CLASSIFICATION

Aerial: Maxar, Microsoft.

- SITE BOUNDARY
 - TURBINE
 - INFRASTRUCTURE
 - PEATLAND CONDITION SURVEY AREA
 - TILE EXTENT/FIGURE NUMBER
- PEATLAND CONDITION**
- ACTIVELY ERODING: HAGG/GULLY
 - DRAINED: ARTIFICIAL
 - DRAINED: HAGG/GULLY
 - MODIFIED
 - NOT PEATLAND



SCALE - 1:22,000 @ A3

ENVIRONMENTAL IMPACT ASSESSMENT REPORT 2025

THIS DRAWING IS THE PROPERTY OF RENEWABLE ENERGY SYSTEMS LTD. AND NO REPRODUCTION MAY BE MADE IN WHOLE OR IN PART WITHOUT PERMISSION